



No	CODE	DESCRIPTION	PIECES
1	12223000000502	Chassis subassembly	1
2	12123000000026	top volute	2
3	12100103000077	centrifuge fan	2
4	12123000000021	bottom volute	2
5	12222500000253	Fan motor axes clamp (left)	1
6	12223000009087	Fan motor fixing board	1
7	12222500000255	Fan motor axes clamp (right)	1
8	11002015000043	Brushless DC Motor	1
9	12223000000567	Fan motor support	1
10	12223000000232	Middle beam subassembly	1
11	12223000000117	Left clapboard subassembly	1
12	15822300000208	Evaporator Assembly	1
12.1	11201007000136	Pipe Temperature Sensor	1
12.2	15122300000480	Evaporator outlet pipe subassembly	1
12.3	15500406000010	Copper nut	1
12.4	15123000000334	Evaporator inlet pipe subassembly	1
12.4.1	15500406000016	Copper nut	1
13	12223000000290	Evaporator right support board subassembly	1
15	12823000000003	Water collector assembly	1
16	12223000000083	Right clapboard assembly	1
17	17223000000226	Electronic control box assembly	1
17.1	12223000000045	Electronic control box	1
17.3	17400401000112	Wire joint	1
17.10	17400306000070	Reactor	1

No	CODE	DESCRIPTION	PIECES
17.6	11201007000143	Room Temperature Sensor	1
17.7	17123000000172	Main control board assembly	1
18	12223000000059	Cover of electronic control box	1
19	12223000000524	Pipe clamp board subassembly	1
20	17223000000003	Duct display board subassembly	1
20.1	17123000000096	Duct main control board subassembly	1
21	17317100A02112	Wired controller	1
22	12223000000260	Rear beam subassembly	1
23	12223000000211	Rear cover subassembly	1
24	12223000000200	Top cover subassembly	1
35	12623000000003	Rubber tube	1
36	17400802000021	Motor subassembly	1
37	12223000000571	Exhaust pump subassembly	1
38	12100510000021	Drain pipe	1
39	12622500000004	Drain pump rubber washer	1
40	12123000000043	Cover of water testing hole	1
41	12622500000003	Drain pump rubber washer	1
43	17222700000159	Electronic control box subassembly	1
43.1	12223000000052	Electronic control box	1
43.2	17122000008562	Inverter control board subassembly	1
43.3	11203803000154	Radiator	1
45	12123000000043	Cover of water testing hole	1
52	12223000A00643	Right clapboard subassembly	1
53	12100204A00155	Air filter	1