



No	CODE	DESCRIPTION	PIECES
1	12223000000515	Chassis Assembly	1
2	12123000000024	top volute	2
3	12100103000079	centrifuge fan	2
4	12123000000022	bottom volute	2
5	12222500000253	Fan motor axes clamp (left)	1
6	12223000000537	Fan motor fixing board	1
7	12222500000255	Fan motor axes clamp (right)	1
8	11002015000344	Brushless DC Motor	1
9	12223000000559	Fan motor support	1
10	12223000000233	Middle beam subassembly	1
11	12223000000122	Left clapboard subassembly	1
12	15823000002165	Evaporator assembly	1
12.1	11201007000136	Pipe Temperature Sensor	1
12.2	15123000000280	Evaporator outlet pipe subassembly	1
12.3	15500406000003	Copper nut	1
12.4	15123000000340	Evaporator inlet pipe subassembly	1
13	12223000000291	Evaporator right support board subassembly	1
14	11201007000266	Pipe Temperature Sensor	1
15	12823000000001	Water collector assembly	1
16	12223000000087	Right clapboard	1
17	17223000000218	Duct electronic control box subassembly	1
17.1	12223000000046	Electronic control box	1
17.3	17400401000026	Wire joint	1
17.10	17400306000070	Reactor	1
17.6	11201007000073	Room temp sensor assembly	1

No	CODE	DESCRIPTION	PIECES
17.7	17123000000162	Duct main control board subassembly	1
18	12223000000060	Cover of electronic control box	1
19	12223000000524	Pipe clamp board subassembly	1
20	17223000000003	Duct display board subassembly	1
20.1	17123000000096	Duct main control board subassembly	1
21	17317100A02112	Wired controller	1
22	12223000000263	Right clapboard	1
23	12223000000217	Rear cover	1
24	12223000000199	Top cover subassembly	1
35	12623000000003	Rubber tube	1
36	17400802000021	Motor subassembly	1
37	12223000000571	Exhaust pump subassembly	1
38	12100510000021	Drain pipe	1
39	12622500000004	Drain pump rubber washer	1
40	12123000000043	Cover of water testing hole	1
41	12622500000003	Drain pump rubber washer	1
42	12223000000547	Fan motor base subassembly	1
43	17222700000162	Electronic control box subassembly	1
43.1	12223000000052	Electronic control box	1
43.2	17122000008498	Inverter control board subassembly	1
43.3	11203803000154	Radiator	1
45	12123000000043	Cover of water testing hole	1
52	12223000000462	Right clapboard subassembly	1
53	12100204000001	Air filter	1